

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY

No. 11165

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080126-4

RECEIVED FROM

PLANT #9

DATE REC'D. 1-31-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO
QUANTITY
RECEIVED

CONTRACT CODE NO.	DRAWING NUMBER	DWG. BASIS OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. CR W.O. NO.	S.O. NO.	REMARKS
322	000000	22066	0	0	0	00	00	R		
DRAWING NO. AND DESCRIPTION								QUANTITY	ACCEPTED	REJECTED
6	736322	BB-BL7 SWITCH BRACKET								

SHIP-TO #85910

RECEIVED
BYINSPECTED
BY

DATE

REJECTS RETURNED
ON SHIP. MEMO NO.

HMC 1069

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2961 E. COLORADO ST., PASADENA, CALIF.

No. 11106

RECEIVED FROM

PLANT #9

DATE REC'D. 1-31-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO
QUANTITY
RECEIVED

CONTRACT CODE NO.	DRAWING NUMBER	DWG. BASIS OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. CR W.O. NO.	S.O. NO.	REMARKS
322	000000	21027	0	0	00	00	00	R		
DRAWING NO. AND DESCRIPTION								QUANTITY	ACCEPTED	REJECTED
84	736316	DOUBLE R LATCH								

SHIP-TO #85911

RECEIVED
BYINSPECTED
BY

DATE

REJECTS RETURNED
ON SHIP. MEMO NO.

HMC 1069

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080126-4